

# Sample Rental Condition Report

Rental: **2-bedroom apartment • Nicosia**

Deposit: **€900**

Generated: **08/07/2026 21:48**

Tenant: **John Doe (john@example.com)**

SAMPLE — NOT A REAL PROPERTY



## Move-in Walkthrough **COMPLETED**

Issues recorded: **2**

**Section:** Kitchen

**Item:** Sink

**Notes:** Small crack near the drain. Water leaks very slightly when running.



**Section:** Walls & Ceilings

**Item:** Cracks

**Notes:** Hairline crack above bedroom door frame.



## Move-out Walkthrough **NOT READY**

No move-out data included in this sample.

Disclaimer: This is a sample PDF for demonstration purposes. TenantPack CY is a documentation tool and does not constitute legal advice.