

Sample Rental Condition Report

Rental: 2-bedroom apartment • Nicosia

Deposit: €900

Generated: 29/04/2026 05:13

Tenant: John Doe (john@example.com)

SAMPLE — NOT A REAL PROPERTY



Move-in Walkthrough COMPLETED

Issues recorded: 2

Section: Kitchen

Item: Sink

Notes: Small crack near the drain. Water leaks very slightly when running.



Section: Walls & Ceilings

Item: Cracks

Notes: Hairline crack above bedroom door frame.



Move-out Walkthrough NOT READY

No move-out data included in this sample.

Disclaimer: This is a sample PDF for demonstration purposes. TenantPack CY is a documentation tool and does not constitute legal advice.